Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: DOBS CTB

Field Name: CEDAR HILLS Well File #:

 Date Incident:
 4/23/2015
 Time Incident:
 08:45
 Facility ID Number:
 413779-03

 County:
 SLOPE
 Twp:
 133
 Rng:
 106
 Sec:
 32
 Qtr:
 SE SE

Location Description:

Submitted By: Patrick Skillestad Received By:

Contact Person: Patrick Skillestad

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 1.3 Barrels 1.3 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

NA

Potential Environmental Impacts:

Soil and gravel in dike.

Action Taken or Planned:

Standing fluid was sucked up and returned to production tanks. Contaminated soil and gravel inside dike was removed and disposed of.

Wastes Disposal Location: Little Missouri Special Landfill

Agencies Involved:

Updates

Date: 4/23/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.